

TUES. 6 SEP 1898

No. 60243.

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 5th Sep 1898 When handed in at Local Office 18

Port of London

No. in
Reg. Book.

Survey held at

London

Date, First Survey

9

Last Survey

1st Sep 1895

(No. of Visits

Master

293 on the Wood, Iron or Steel 88 "Thermopylae"

TONNAGE:-

Built at Aberdeen

By whom Hall Russell & Co

When 1891

YEAR.

MONTH.

GROSS 3711

Owners

G. Thompson & Co

Port belonging to Aberdeen

UNDER DK. 3496

Owners' Address

NET 2396

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock?

Name of Dock Albert

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; J

feet; }

total capacity

tons. FBT

tons; APT

tons; MT

feet

tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.Years
Assigned
now
expired.Machinery and Boiler
Surveys
(including date of N.B., if any).

* 100A1

* LMC 8.96

Spar De

BS 11.97

4.98

88 Jan 20-96

Society's Freeboard (if assigned) as

painted on Ship and now verified

ft. ins.

Last Report, No. 59812 Port Lon

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Condition

The bottom has been examined in dry dock, cleaned & coated.

SUMMARY OF DAMAGE REPAIRS:-

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Decks	good	Stringers	✓	Engine Room Skylights	good	Boats	good
Caulking of Decks	"	Inner Bottom Plating	✓	Coal Bunkers, Open'gs, Lids, &c.	"	Masts, Yards, &c.	"
Waterways	"	State if Tanks now tested	✓	Scuppers	"	Condition, how ascertained	frank
Coamings	"	Bulkheads	✓	Cargo Hatchways	"	(State if wedges removed)	no
Beams & Fastenings	✓	Ceiling	✓	Hatches	"	Sails	✓
Outside Plating	"	Cement or Asphalt	✓	Planking of Wood Vessels	"	Equipment letter	w
Caulking of ditto	"	(State which.)	"	Treenails	ditto	Anchors, No. of	6
Rivets	"	Rudder	good	Breasthooks & Stemson	ditto	Cables (State if now ranged)	no
Breasthooks & Crutches	✓	Windlass	"	Transoms, Pointers, & Crutches	ditto	" length (on board)	✓
Transoms	✓	Have Pumps now been examined and found efficient?	✓	Timbers of Frame at openings	ditto	" Rule length (per Table 22)	size
Frames	✓	Have Sluice Valves now been examined and found efficient?	✓	Ditto ditto at other places	ditto	Hawsers & Warps	good
Reverse Frames	✓	Have Watertight Doors now been examined and found efficient?	✓	Salting (State if examined.)	ditto	Standing & Running Rigging	"
Floors	✓	Have Watertight Doors now been examined and found efficient?	✓	Copper, or Y.M. (State if on Felt.)	ditto		
Keelsons	✓	Dbng. Plates under Sounding Pipes	✓	When put on, Month	Year		

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel now appears to be in good condition, & is eligible in my opinion to remain as classed with record of survey - 9.98

Office Fee (if chargeable) per Scale II, Sec. 27 £

Survey Fee (per Section 25) £

Special Damage or Repair Fee (if any) (per Sec. 25.) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

18

Received by me,

18

Alampbell & Co
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRI. 9 SEP 1898

100A1 Spar & Co



© 2019

Lloyd's Register Foundation

LON716-0305

Has a Survey also been held on the Machinery of the Ship?
If so, is the Report sent now, or when will it be sent?

3481-5000-4708-Transfer Ink
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

Is Certificate required? If so to be sent to