

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18 When handed in at Local Office 18 Port of London

No. in Reg. Book 779 on the Wood, Iron or Steel S.S. Minnesota Master Starling Wolff
Survey held at London Date, First Survey 1887-11 Last Survey Oct 22 1898
TONNAGE: GROSS 3216 Built at Belfast By whom Starling Wolff
UNDER DEK 2988 Owners Atlantic Transport Co. Ltd. Port belonging to London
NET 2080 Owners' Address (William J. Jorrey & Co. Ltd.)
(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Name of Dock W. J. Fray. Dk. Destined Voyage New York etc

WB=CellDBorDBa feet; uE&B feet; J feet; Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
Total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
The vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, of the inner bottom plating, especially in the boiler space.
Lloyd's Port, No. 60264 Port Pen
Period when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs (the cause of which must be stated) should be separated from Repairs due to other causes; and besides repairs in the body of the report, should be summarised in the form shown below. Whenever the replacement of masts, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.
Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition after alleged grounding.

Bottom cleaned, examined & re-coated
Rudders re-bushed & two new pintles fitted.

The S.S. N.P. 1 has not been advanced. The Superintendent states this will be done on the vessel's return from her present voyage.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats
Decks	good	good	good
Caulking of Decks			
Waterways			
Coamings			
Beams & Fastenings			
Outside Plating			
Caulking of ditto			
Rivets			
Breasthooks & Crutches			
Transoms			
Frames			
Reverse Frames			
Floors			
Keelsons			

Inner Bottom Plating	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
State if Tanks now tested		
Bulkheads		
Ceiling		
Cement or Asphalt (State which.)		
Rudder		
Windlass		
Have Pumps now been examined and found efficient?		
Have Sluice Valves now been examined and found efficient?		
Have Watertight Doors now been examined and found efficient?		
Dblg. Plates under Sounding Pipes		

Scuppers	Cargo Hatchways	Condition, how ascertained
		(State if wedges removed)
Hatches		
Planking of Wood Vessels		
Treenails		
Breasthooks & Stemson		
Transoms, Pointers, & Crutches		
Timbers of Frame at openings		
Ditto ditto at other places		
Stringers, Clamps & Shelves		
Salting (State if examined.)		
Copper, or Y.M. (State if on felt.)		
When put on, Month		

Sails	Equipment letter	Anchors, No. of

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."
This vessel appears to be in good condition & eligible in my opinion to remain as classed without fresh record of survey.

Office Fee (if chargeable) per Scale II, Sec. 27 £
Survey Fee (per Section 25) £
Special Damage or Repair Fee (if any) (per Sec. 26) £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £
Fees applied for, 3/11/99
Received by me, 4-11-99
C. Marshall
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Character assigned Deferred for completion of report
TUES. 13 DEC 1898
FRI. 27 JAN 1899
FRI. 24 MAR 1899
TUES. 4 JUL 1899
Lloyd's Register Foundation
LON 717-0113