

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 9-1-99 When handed in at Local Office 9-1-99 18. Port of London
 No. in Reg. Book. Survey held at London Date, First Survey 23.12.98 Last Survey 9-1-99
 3-15 on the Wood, Iron or Steel BR GLAMIS (No. of Visits 9) Master W.C. Davay 9-1-99
 TONNAGE:- Built at Dundee By whom A. Stepland & Co When 1896-9 mo.

GROSS 1205 Owners D. Bruce & Co Port belonging to Dundee
 UNDER DEK 1076 Owners' Address
 NET 1099 (if not already reported in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Browns Dock Destined Voyage East London
 WB=CellDBorDBd feet; uE&B feet; I feet; }
 total capacity tons FBT tons; APT tons; MT feet tons. }
 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
 If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 59168 Port Lon

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This vessel was placed in dry dock the bottom examined cleaned & recoated

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Faired or Repaired ...								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Stringers	Inner Bottom Plating	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt (State if examined)	Rudder	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblg. Plates under Sounding Pipes
Decks	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Caulking of Decks	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Waterways	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Coamings	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Beams & Fastenings	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Outside Plating	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Caulking of ditto	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Rivets	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Breasthooks & Crutches	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Transoms	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Frames	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Reverse Frames	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Floors	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Keelsons	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good

General Observations, Opinion as to Class, Recommendation, &c.:—	Boats	Masts, Yards, &c.	Condition, how ascertained	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	length	size	Hawsers & Warps	Standing & Running Rigging
	Good	Good	from dks	stated good		3B-1S-2K	no	skated complete	good	good	good

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and pND98, &c."

This vessel now appears to be in good condition eligible in my opinion to remain as classed with a fresh record of survey Lon 1/99-

Office Fee (if chargeable) per Scale II., Sec. 27	£	:	:	Fees applied for,
Survey Fee (per Section 28)	£	:	:	18
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	18
Second Surveyor's Fee (if any)	£	:	:	

Edward J.W. Tierney

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRI. 13 JAN 1899

LOOAN



© 2019

Lloyd's Register Foundation

LON 717-0236