

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 1891 When handed in at Lloyd's Office 1891 Port of London  
No. in Reg. Book 1231 Survey held at 1891 Date, First Survey 1880 Last Survey 1891  
Built at Port Glasgow By whom Blackwood & Gordon When 1880  
GROSS 1231 Owners General Steam Nav. Co Port belonging to London  
UNDER DE. 957  
NET 778 Owners' Address  
(If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage  
WB=CellDBorDBa feet; uE&B feet; total capacity tons. FPT tons; APT tons. MT tons.

N.B.—All alterations in the existing records should be underlined.  
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, plating, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 60431 Port London

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								
PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats					
Decks	Inner Bottom Plating	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.					
Caulking of Decks	State if Tanks now tested	Scuppers	Condition, how ascertained					
Waterways	Bulkheads	Cargo Hatchways	(State if wedges removed)					
Coamings	Ceiling	Hatches	Sails					
Beams & Fastenings	Cement or Asphalt (State which.)	Planking of Wood Vessels	Equipment letter					
Outside Plating	Edder	Treenails ditto	Anchors, No. of					
Caulking of ditto	Windlass	Breasthooks & Stems ditto	Cables (state if now ranged)					
Rivets	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" length (on board) size					
Breasthooks & Crutches	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	" Rule length (per Table 22) size					
Transoms	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Hawsers & Warps					
Frames	Have Watertight Doors now been examined and found efficient?	Stringers, Clamps & Shells ditto	Standing & Running Rigging					
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Salting (State if examined.) ditto						
Floors	Have Watertight Doors now been examined and found efficient?	Copper, or Y.M. (State if on felt.) ditto						
Keelsons	When put on, Month Year							
	Dbing. Plates under Sounding Pipes							

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,
Survey Fee (per Section 28)	£	18
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	Received by me,
Travelling Expenses (if chargeable)	£	18
Second Surveyor's Fee (if any)	£	

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

Withdrawn class & insert

© 2019 Lloyd's Register Foundation