

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 12-6-99 When handed in at Local Office 12-6-99 Port of London

No. in Reg. Book 33 Survey held at London Date, First Survey Jun 6 Last Survey Jun 1899

on the Wooden Steel ss Barlington Master Hardy 95

TONNAGE:— Built at Sunderland By whom S.P. Austin When 1895-5

GROSS 1032 Owners' Address P.O. Steam Nav Co Port belonging to London

UNDER DE 753 Owners' Address (if not already recorded in Appendix to Register Book.)

NET 627 Surveyed Afloat or in Dry Dock Afloat Name of Dock Royal Albert Dock Destination Voyage Tyne

WB=Cell DBor DBa feet; uE&B feet; feet; feet; Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT feet tons. +100AL. 5/99 + RMC 5/99

N.B.—All alterations in the existing records should be underlined. If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 61047 Port London Society's Freeboard (if assigned) as painted on Ship and now verified 1 5/8 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of SS not.

This steamer was seen afloat in the Royal Albert Dock, and the starboard side bunkers, cleared & examined & tank top & sides. cleaned & recoated

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								
PRESENT CONDITION OF THE								
Decks	Good	Stringers	Good	Engine Room Skylights	Good	Boats	Good	
Caulking of Decks	"	Inner Bottom Plating	"	Coal Bunkers, Open'gs, Lids, &c.	"	Masts, Yards, &c.	"	
Waterways	"	State if Tanks now tested	"	Scuppers	"	Condition, how ascertained	from DR	
Coamings	"	Bulkheads	"	Cargo Hatchways	"	(State if wedges removed	no	
Beams & Fastenings	"	Ceiling	"	Hatches	"	Sails	good	
Outside Plating	"	Cement or Asphalt	"	Planking of Wood Vessels	"	Equipment letter		
Caulking of ditto	"	(State if exp.)	"	Treenails	ditto	Anchors, No. of	83-18-2K	
Rivets	"	Rudder	"	Breasthooks & Stemson	ditto	Cables (State if now ranged)	no	
Breasthooks & Crutches	"	Windlass	"	Transoms, Pointers, & Crutches	ditto	"	Shaded	
Transoms	"	Have Pumps now been examined and found efficient?	"	Timbers of Frame at openings	ditto	Rule length	Complete	
Frames	"	Have Sluice Valves now been examined and found efficient?	"	Ditto ditto at other places	ditto	(per Table 22)	for	
Reverse Frames	"	Have Watertight Doors now been examined and found efficient?	"	Stringers, Clamps & Shelves	ditto	Hawsers & Warps		
Floors	"	Dblng. Plates under Sounding Pipes	"	Salting	ditto	Standing & Running Rigging		
Keelsons	"			(State if examined.)				
				Copper, or Y.M.	ditto			
				(State if on felt.)				
				When put on, Month	Year			

General Observations, Opinion as to Class, Recommendation, &c.:— State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This steamer now appears to be in good condition, eligible in my opinion to remain as classed, with a fresh record of survey & the notation for SS not noted

Office Fee (if chargeable) per Scale II, Sec. 27 £ : : Fees applied for, 12/6 18 99
Survey Fee (per Section 28) £ 4 : : Received by me, Edward J. W. L. L. L.
Special Damage or Repair Fee (if any) (per Sec. 28.) £ 3 : 12 : 0
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute TUES. 13 JUN 1899
Character assigned 100A1

no. 1-99
Lloyd's Register Foundation