

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 24 July 1899 When handed in at Local Office 18 Port of London
No. in Survey held at London Date, First Survey 4 Last Survey 21 July 1899
Reg. Book. 120 on the Wood, Iron or Steel & Canterbury Master
(No. of Visits)

TONNAGE:- Built at Pt Glasgow By whom R Duncan & Co When 1874
GROSS 1309 Owners Shaw Savill & Albion Co Port belonging to Glasgow
UNDER DEK 1126
NET 1245 Owners' Address
(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Name of Dock Orchard St Destined Voyage

WB=CellDBorDBa feet; uE&B feet; J feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 60265 Port London

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

The bottom has been examined in dry dock, cleaned and coated, and the rudder has been lashed.

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Decks	good	Stringers	✓	Engine Room Skylights	✓	Boats	good
Caulking of Decks	"	Inner Bottom Plating	✓	Coal Bunkers, Open'gs, Lids, &c.	✓	Masts, Yards, &c.	"
Waterways	"	State of Tanks now tested	✓	Scuppers	good	Condition, how ascertained	"
Coamings	"	Bulkheads	✓	Cargo Hatchways	"	(State if wedges removed from Dk.)	✓
Beams & Fastenings	✓	Ceiling	✓	Hatches	"	Sails	✓
Outside Plating	good	Cement or Asphalt	✓	Planking of Wood Vessels	"	Equipment letter	S
Caulking of ditto	"	(State which.)	✓	Treenails	ditto	Anchors, No. of	5
Rivets	"	Rudder	good	Breasthooks & Stemson	ditto	Cables (State if now ranged)	no
Breasthooks & Crutches	✓	Windlass	"	Transoms, Pointers, & Crutches	ditto	" length (on board)	size
Transoms	✓	Have Pumps now been examined and found efficient?	✓	Timbers of Frame at openings	ditto	" Rule length (per Table 22)	✓ size
Frames	✓	Have Sluice Valves now been examined and found efficient?	✓	Ditto ditto at other places	ditto	Hawsers & Warps	good
Reverse Frames	✓	Have Watertight Doors now been examined and found efficient?	✓	Stringers, Clamps & Shelves	ditto	Standing & Running Rigging	"
Floors	✓	Have Watertight Doors now been examined and found efficient?	✓	Salting (State if examined.)	ditto		
Keelsons	✓	efficient?	✓	Copper, or Y.M. (State if on Felt.)	ditto		
		Dblng. Plates under Sounding Pipes	✓	When put on, Month	Year		

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptd98, &c."

This vessel now appears to be in good condition & is eligible in my opinion to remain as classed with record of survey 7.99

Office Fee (if chargeable) per Scale II., Sec. 27 £

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) (per Sec. 28.) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

18.

Received by me,

18.

Alampheestelms
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRI. 28 JUL 1899

100A1



© 2019

Lloyd's Register
Foundation

Lon 719 - 0027