

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18. When handed in at Local Office 18. Port of London

No. in Reg. Book 424 Survey held at London Date, First Survey 29-7 Last Survey 3-8 1899

on the Wood, Iron Steel S.S. Lisbon Master Denton Gray H.

TONNAGE: 1334 Built at N. Hartlepool By whom J. Hall & H. Owners' Address

GROSS 1334 Owners' Address J. Hall & H. Port belonging to London

UNDER DE 1294 Owners' Address J. Hall & H. Port belonging to London

NET 860 Owners' Address J. Hall & H. Port belonging to London

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Fletcher Destined Voyage

WB=CellDBorDBa feet; uE&B feet; J feet; Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT feet tons. Society's Freeboard (if assigned) as painted on Ship and now verified

N.B.—All alterations in the existing records should be underlined. If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 60152 Port Lon

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repair on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition (after having been on the ground)

This vessel has now been placed in dry dock - bottom found sound and abraded: has now been cleaned and recoated. Rudder examined & retouched

## SUMMARY OF DAMAGE REPAIRS :—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

## PRESENT CONDITION OF THE

Decks	grd	Stringers	grd	Engine Room Skylights	grd	Boats	grd
Caulking of Decks	grd	Inner Bottom Plating	grd	Coal Bunkers, Open'gs, Lids, &c.	grd	Masts, Yards, &c.	grd
Waterways	grd	State if Tanks now tested	grd	Scuppers	grd	Condition, how ascertained	from deck
Coamings	grd	Bulkheads	grd	Cargo Hatchways	grd	(State if wedges removed)	
Beams & Fastenings	grd	Ceiling	grd	Hatches	grd	Sails	grd
Outside Plating	grd	Cement or Asphalt	not seen	Planking of Wood Vessels	grd	Equipment letter	grd
Caulking of ditto	grd	(State which.)		Treenails	ditto	Anchors, No. of	3/3 1/2 2H
Rivets	grd	Rudder	grd	Breasthooks & Stemson	ditto	Cables (State if now ranged)	grd
Breasthooks & Crutches	not seen	Windlass	grd	Transoms, Pointers, & Crutches	ditto	length (on board)	grd
Transoms	grd	Have Pumps now been examined and found efficient?	grd	Timbers of Frame at openings	ditto	Rule length (per Table 22)	grd
Frames	grd	Have Sluice Valves now been examined and found efficient?	grd	Ditto ditto at other places	ditto	Hawsers & Warps	grd
Reverse Frames	grd	Have Watertight Doors now been examined and found efficient?	grd	Stringers, Clamps & Shells	ditto	Standing & Running Rigging	grd
Floors	not seen	Salting (State if examined.)	grd	Copper, or Y.M. (State if on Felt.)	ditto		
Keelsons	grd	When put on, Month	grd				
		Dblng. Plates under Sounding Pipes	grd				

## General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel appears to be in good condition & is eligible for my opinion to remain as classed with record of survey 1899

Office Fee (if chargeable) per Scale II., Sec. 27	£			
Survey Fee (per Section 28)	£			
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	2	2	0
Travelling Expenses (if chargeable)	£	4	0	0
Second Surveyor's Fee (if any)	£	1	18	0

Fees applied for, 5/8 18.99

Received by me, 9.8 18.99

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

rb8

TUES. 8 AUG 1899

100A



© 2019

Lloyd's Register Foundation

Lon 7/9 - 0093