

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 9th Aug 1899 When handed in at Local Office 18th Port of London
No. in Reg. Book. Survey held at London Date, First Survey 28th July Last Survey 5th Aug 1899
(No. of Visits) 4 Master
992 on the Wood, Iron or Steel & Crusader
TONNAGE:- Built at Glasgow By whom O Connell & Co When 1865 3
GROSS 1099 Owners O'Brien
UNDER DEK. 973 Owners' Address
NET 996 (if not already recorded in Appendix to Register Book.)
Port belonging to Christiania

Surveyed Afloat or in Dry Dock? Name of Dock Orchard Destined Voyage

WB=CellDBorDBa feet; uE&B feet; J feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 60035 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Damage by collision in the river

The bottom has been examined in dry dock, cleaned & coated
The first stem plate, Port side, strike below sheer broken, and two frames & one reverse bar bent. The broken plate has been partly renewed & the two bent frames repaired in place.

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...	1 (port)	✓	✓					
Removed and Fair'd or Repaired ...	✓	✓	✓					
Fair'd or Repaired in place ...	✓	2	1					

PRESENT CONDITION OF THE

Decks	good	Stringers	✓	Engine Room Skylights	✓	Boats	good
Caulking of Decks	✓	Inner Bottom Plating	✓	Coal Bunkers, Open'gs, Lids, &c.	✓	Masts, Yards, &c.	✓
Waterways	✓	State of Tanks now tested	✓	Scuppers	✓	Condition, how ascertained	from deck
Coamings	✓	Bulkheads	✓	Cargo Hatchways	✓	(State if wedges removed	no)
Beams & Fastenings	✓	Ceiling	✓	Hatches	✓	Sails	✓
Outside Plating	✓	Cement or Asphalt (State which.)	✓	Planking of Wood Vessels	✓	Equipment letter	✓
Caulking of ditto	✓	Rudder	good	Treenails ditto	✓	Anchors, No. of	6
Rivets	✓	Windlass	✓	Breasthooks & Stemson ditto	✓	Cables (State if now ranged)	no
Breasthooks & Crutches	✓	Have Pumps now been examined and found efficient?	no	Transoms, Pointers, & Crutches ditto	✓	" length (on board)	✓
Transoms	✓	Have Sluice Valves now been examined and found efficient?	no	Timbers of Frame at openings ditto	✓	" Rule length (per Table 22)	✓
Frames	✓	Have Watertight Doors now been examined and found efficient?	✓	Ditto ditto at other places ditto	✓	Hawsers & Warps	good
Reverse Frames	✓			Stringers, Clamps & Shelves ditto	✓	Standing & Running Rigging	✓
Floors	✓			Salting (State if examined.) ditto	✓		
Keelsons	✓			Copper, or Y.M. (State if on felt.) ditto	✓		
		Dblg. Plates under Sounding Pipes	✓	When put on, Month	✓		

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any, and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel appears to be in good condition & is eligible in my opinion to remain as classed with record of survey 8,99

Office Fee (if chargeable) per Scale II., Sec. 27£

Survey Fee (per Section 28)£

Special Damage or Repair Fee (if any) (per Sec. 28.)£

Travelling Expenses (if chargeable)£

Second Surveyor's Fee (if any)£

Fees applied for,

18.....

Received by me,

18.....

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRI 11 AUG 1899

A



© 2019

Lloyd's Register

Foundation

LON 719 - 0108