

REPORT of SURVEY for REPAIRS, &c

Date of writing Report 3-8-99 When handed in at Local Office 3-8-99 Port of London
 No. in Survey held at London Date First Survey Aug 1 Last Survey 3-8-99
 Reg. Book 912 on the *Wardman Steel* of *Pembroke Castle* Master

TONNAGE:— Built at *Barrow* By whom *Barrow S. B. & Co* When 1883-7
 GROSS 4075 Owners *(D Currie & Co mgs)* Port belonging to *London*
 UNDER 2639 Owners' Address
 NET 2571 (if not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock *Dry Dock* Name of Dock *Shames R* Destined Voyage *Cape*
 WB=CellDBorDBa feet; uEB feet; I feet; }
 total capacity tons. FPT tons; APT tons; MT feet tons. }
 N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 61056 Port *Low*

(Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes, and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. Year Assigned now expired. Machinery and Boiler Surveys (including date of N.B., if any).

+100A 1. 599 +1385799 +hmc 12/95

S. 396 103-12/95

Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Condition
 This steamer was placed in the *Shames* Limited dry dock. The bottom examined cleaned and recoated.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Paired or Repaired ...								
Paired or Repaired in place ...								
PRESENT CONDITION OF THE								
Decks <i>Good</i>	Stringers <i>Good</i>				Engine Room Skylights <i>Good</i>			Boats <i>Good</i>
Caulking of Decks	Inner Bottom Plating				Coal Bunkers, Open'gs, Lids, &c.			Masts, Yards, &c.
Waterways	State if Tanks now tested				Souppers			Condition, how ascertained <i>from dr</i>
Coamings	Bulkheads				Cargo Hatchways			(State if wedges removed <i>no</i>)
Beams & Fastenings	Ceiling				Hatches			Sails <i>good</i>
Outside Plating	Cement or Asphalt (State if tested)				Planking of Wood Vessels			Equipment letter <i>W</i>
Caulking of ditto	Rudder				Treenails ditto			Anchors, No. of <i>6</i>
Rivets	Windlass				Breasthooks & Stemson ditto			Cables (State if now ranged <i>no</i>)
Breasthooks & Crutches	Have Pumps now been examined and found efficient?				Transoms, Pointers, & Cratches ditto			" length size <i>Stated Complete</i>
Transoms	Have Sluice Valves now been examined and found efficient?				Timbers of Frame at openings ditto			" Rule length size (per Table 22)
Frames	Have Watertight Doors now been examined and found efficient?				Ditto ditto at other places ditto			Hawsers & Warps <i>good</i>
Reverse Frames					Stringers, Clamps & Shelves ditto			Standing & Running Rigging
Floors					Salting (State if examined.) ditto			
Keelsons					Copper, or Y.M. (State if on felt.) ditto			
	Dblg. Plates under Sounding Pipes				When put on, Month Year			

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This steamer now appears to be in good condition eligible in my opinion to remain as classed with a fresh record of Survey Low 899

Office Fee (if chargeable) per Scale II, Sec. 24

Survey Fee (per Section 25)

Special Damage or Repair Fee (if any) (per Sec. 25.)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for

Received by me,

Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute

Character assigned

FRI 11 AUG 1899

100A 1



© 2019

Lloyd's Register Foundation

Low 719-0111