

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 15th Sep 99 When handed in at Local Office London is 1899 Port of London
 No. in Survey held at London Date, First Survey 28th Aug 99 Last Survey 11th Sep 99
 Reg. Book. 10 on the Wood, Iron or Steel S. Jarkand (No. of Visits) 4 Master 4

TONNAGE:— Built at Barrow By whom Barrow S.B.C. When 1877-1
 GROSS 1352 Owners Stippard & Co. Rangoon Port belonging to Rangoon
 UNDER DE. 1240 Owners' Address -
 NET 1511 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? 2 Name of Dock Blas P. 7. K Destined Voyage -

WB=Cell DBor DBa - feet; uE&B - feet; J - feet;
 total capacity - tons. FPT - tons; APT - tons; MT - feet - tons.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ☒ for Special Survey. Date of last Survey and of Periodical Surveys. Years Assigned. Expired. Machinery and Boiler Surveys (including date of N.B., if any).

+100 A 1

9.98
 S.S. 2.09
 S. 9 112.98

Society's Freeboard (if assigned) as painted on Ship and now verified - ft. - ins.

Last Report, No. 3820 Port Out

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

Steel and bottom examined in dry dock. Under overhauled, and bottom cleaned and repainted.

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	Stringers	Engine Room Skylights	Boats
Caulking of Decks	Inner Bottom Plating	Coal Bunkers, Openings, Lids, &c.	Masts, Yards, &c.
Waterways	State if Tanks now tested	Scuppers	Condition, how ascertained
Coamings	Bulkheads	Cargo Hatchways	(State if wedges removed)
Beams & Fastenings	Ceiling	Hatches	Sails
Outside Plating	Cement or Asphalt	Planking of Wood Vessels	Equipment letter
Caulking of ditto	(State which.)	Treenails	Anchors, No. of
Rivets	Rudder	Breasthooks & Stemson	Cables (State if now ranged)
Breasthooks & Crutches	Windlass	Transoms, Pointers, & Crutches	" length (on board)
Transoms	Have Pumps now been examined and found efficient?	Timbers of Frame at openings	" Rule length (per Table 22)
Frames	Have Sluice Valves now been examined and found efficient?	Ditto ditto at other places	Hawsers & Warps
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Stringers, Clamps & Shells	Standing & Running Rigging
Floors	Have Watertight Doors now been examined and found efficient?	Salting (State if examined.)	
Keelsons	Dbing. Plates under Sounding Pipes	Copper or Y.M. (State if on felt.)	
		When put on, Month	
		Year	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel is now in good and efficient condition, and eligible to remain as Classed with record 9.99.

Office Fee (if chargeable) per Scale II., Sec. 27£
 Survey Fee (per Section 28)£
 Special Damage or Repair Fee (if any) (per Sec. 28.)£
 Travelling Expenses (if chargeable)£
 Second Surveyor's Fee (if any)£

Fees applied for,

18.

Received by me,

18.

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUES 19 SEP 1899

Character assigned



© 2019

Lloyd's Register Foundation

Lon 719 - 0276