

Dear Sir,

20th June, 1894

17th inst.

donkey

Wolfe

loan

at your

the s.s.

So

the rivet holes of the longitudinal seams of the shell be $2\frac{3}{4}$ " pitch; the steel used be such as required by the Rules; & the boiler in other respects be built in accordance with the plan, under the usual conditions of survey and testing and to the entire satisfaction of the Local Engineer.

The plan referred to is returned herewith.

I also enclose a special survey order form, which kindly sign & return to me, together with the plan, at your convenience.

Yours faithfully,

John Creaton Esq.

Gen. Secy. R.S.O. Co.

Deptford, S.E.



© 2021

Lloyd's Register
Foundation