

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

*S.S. "Lagass"*

Report

No.

For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Clas sing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Clas sing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*Removal of donkey boiler* When due *The old donkey boiler due for survey  
March 1896*

The old donkey boiler has now been removed from the vessel & a new one has been fitted on board, but the mountings are not yet fitted on the boiler.

The Owners propose to have the donkey boiler completed, & the safety valves adjusted, on the vessel's return to London in about six weeks & at the same time they propose to have the H.P. slide valve examined.

It is submitted that the Owners' proposal be approved.



© 2021

1.1.96  
Lloyd's Register  
Foundation

LON729-0286