

Lloyd's Register of British and Foreign Shipping.

(Report on Vessel No. 9098 Port Leith)No. 6889 SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned Iron or Steel Forgings or Castings, manufactured by Messrs The Ayrshire Foundry Co. (Ld.) of Strenston for the Vessel No. 105, being built by Messrs John Scott & Co. of Kinghorn have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects.

Mark on

Castings

Lloyd's

No. 6889R. J.J. J. Dodd.Glasgow 22.2.99

	<u>Two</u> STERN <u>Brackets</u>	RUDDER FRAME.	STEM.
Material*	<u>Cast Steel</u>		
How made	<u>Siemens' Process</u>		
Dimensions	<u>As per pattern received from Builders</u>		
Progress on Inspection	<u>Cast</u>		
Date when Inspected	<u>Jan'y 31st, Feb'y 14, 16th, 18th & 20th 1899.</u>		

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS, OR PARTICULARS OF TESTS APPLIED TO CASTINGS.

Samples cut from the two Stem Brackets have been subjected, in my presence to the tensile and bending tests required by the Rules of this Society and found satisfactory.
The castings have also been dropped, hammered and afterwards examined.

Fee (if any chargeable) £ : :

To be paid at

John S. P. Cloughton

Lth. Sept 9098



© 2019

Lloyd's Register
Foundation