

s/s Camel

It is submitted that before dealing with
this case the report should be returned to the
wrecker & he be requested to fill in the
particulars of the Brank & Tunnel shafting

to be sent

28/5/97



7/1
28/5/97

© 2019

Lloyd's Register
Foundation

MDG756-0221

the damage & minor repairs made good.