

F.E.

Received by Chief Surveyor 11. 5. 99

Received from Chief Surveyor _____

EL'S NAME Sa. S. S. "Novington" Report made No. 2589

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>2/20"</u>	<u>Proportion</u>
Spar Sheerstrake . .	<u>✓</u>	<u>✓</u>
Description of Framing:— <u>Deep framing.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed $\pm 100 A 1$ ("Steel") as recommended.

$\pm 100 A 1$ ("Steel")

1 DR (1st Int & 1st Stk) & deep framing.

W. B = Cell DB a 110' u E 24' f 128' 6696 APT 41E

FK 5BH Cenn. Lloyd A & CP.

C. H. J.
11/5/99



© 2019

Lloyd's Register

MDB762-0086