

Reference

Lloyd's Register of British  
and Foreign Shipping.

LLOYD'S REGISTER  
LONDON.

RECEIVED 16 MAR. 91

ANSW.

Priory Road Milford Haven

14<sup>th</sup> March 1891

Sir

In reply to your letter of the 13<sup>th</sup> inst. Re  
"Speke" I beg to state that the rivets in the  
landing edges are 4" Centres as marked on the  
Report; I understood from the rules that if  
the spacing of rivets of  $\frac{7}{8}$ " diamr. did not exceed  
4" the maximum distance they would do.

Mr Adwals Manager before the vessels<sup>(2598260)</sup> were  
commenced shew me how they proposed to space  
the rivets and told me they had never spaced  
them differently and finding it did not exceed  
4" I did not object.

The Certificates for the steel wire Hawsers I send  
herewith, and the Report has been signed as  
directed.

I am Sir  
your obedient servant  
J. E. Secombe  
Surveyor



Referred to the Chief Surveyor.

agp

16.3.91

LRF-P4N-MIL769-0255-L



© 2021

Lloyd's Register  
Foundation