

Lloyds Register of British
and Foreign Shipping.

Priory Road Milford Haven

11th Decr 1891

Sir

I have not been able as yet to make out the report on damage to ship Windermere they got a stage rigged this forenoon and I find the shell plate where the vessel has grazed along the Pier will have to be renewed

I have shown Captain Tickle the Owners representative both ways of repairing this, one way to scarf the frame and give compensation, the other if he wishes the frame angles in one as before to strip the shell plates to nearly the keel to get the iron in he is waiting to hear from his owners I will likely hear from him tonight

I am, Sir,

your obedient Servant

②821
A. D. Allan

Lloyd's Register
Foundation

The Secretary
London



LLOYDS' REGISTER.

LONDON.

RECP 12 DEC 91

ANSR

Mil: A. 11.1.D.
Hibbs

H. Allen.

re damage to s.
"Windermere
Ingenier"



© 2012 Lloyd's Register Foundation