

East Holborn, St. Shields.  
Newcastle 193

Mr Popham

253

Sir

in 1830

the ship was rebuilt & repaired in  
Messrs Straker and Edwards Dock  
which cost upwards of £800.

in the latter part of 1832 had in How-  
den Dock, new Floors, Main Relson,  
Beams, &c, all Oak, since that has  
had new Pinnas, new Stern, quarter  
Timbers Stern &c. if you wish for any  
further Information, please send by  
the Bearer I am Sir with great  
Respect, Yours,



© 2018

Lloyd's Register  
Foundation



Mr M Popplewell

Lloyd's Surveyor

No 29 Dockway

North Shields.