

1st. On the several parts of the frame, when in place, and before the plating was wrought  
2nd. On the plating during the process of riveting

1802. Mar. 14. Apr. 8. 15. 21. 23. 29. 30. 31. Sep. 7. 8. 11. 12. 13. 15. 16. 21. 22. 25. 27.

NWC 785-0212

REPORT, No. *16800* FROM *Newcastle*  
ON THE *Anglo Indian*  
REMARKS OF THE CHIEF SURVEYOR.


DATE *6/7/83*

It is submitted that this vessel has been built in accordance with the accompanying approved plans, and appears eligible to be classed 100A1 "Spar Decked" as recommended.

*"1st & Spar Deck" 2 hon. decks*

*3 tns of Bms.*

*Double bottom - particulars attached*



© 2021

Lloyd's Register  
Foundation

*two lower breasthooks, breasthook angle iron shoe, a few stringer*