

No. 2349

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received in London Office, 11/11/83)

TESTS OF BOILER STEEL.

Tests of 14 Steel Plates manufactured by Messrs D. Colville & Sons of Motherwell for Boiler No. 194 to be constructed by Messrs Wigham Richardson & Co of Newcastle for their S. S. No. 194

Date first visit April 29-1883 last visit

No. of Visits

The specified in the accompanying copy of Advice Notes were rolled from charges. The tensile test has been applied to 2 samples as set forth below, and the temper and bending tests as required by Circular No. 430

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	Top of Back	9537		7052	.93	1.39	1.292	36.40	28.1	29.0	
2	Centre of Back	7984		6452	.83	1.57	1.303	37.02	28.4	28.0	

M 13/5/83

Fee ..... £ : :

Expenses £ : :

£ : :

To be paid by



© 2021

H. M. Jones  
Surveyor, Lloyd's Register,  
Glasgow

D.P.  
12/5/85

S.S. "Baghdadi"  
Nwc. Report No 18619



© 2021

Lloyd's Register  
Foundation