

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING

No. 4542

TESTS OF BOILER STEEL.

Tests of 6 Steel Plates manufactured by Messrs W. Beardmore & Co. of Parkhead
for Boiler No. 483 to be constructed by Palmers & Co. Ltd of Glasgow.
for

Date first visit *March 11th* last visit *do* No. of visits *One*

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to one samples as set forth below, and the temper and bending tests to a sample of each plate

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	Boiler plate	A200		678	.54	1.08	.583	16.45	29.	26	5'-3" x 69" x $\frac{17}{32}$ "
W.P. 7/4/87											

Fee £ : :

Expenses £ : :

£ : :

To be paid by

Surveyor, Lloyd's Register.

© 2021

Surveyor, Lloyd's Register,
London.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.