

Messrs Blair & Co. (Ltd) Stockton

April 6th 7

15
201

957

3 March 4 W'dale Lx: Still plates

18.9 x 5.0³/₄ = 1¹/₁₆

4 . 18.5¹/₂ x 5.9³/₄ =

3 . 2.4 x 2.0 =

3 . 1.8 x 1.4 = 1.0

6 . 6.0 x 2.11¹/₂ = ³/₁₆

6 . 5.1 =

6 . 7.8 =

12 . 3.11 x 1.9¹/₂ = 7⁷/₈

3 March 12 3.4 x 6.0²/₄ = ¹¹/₁₆

11.9 x 5.0²/₄ = 8¹/₁₆

46 . 10.4 x 5.4 Sketch = 1¹/₁₆

5 . 5.7 x 1.5²/₄ = 7¹/₁₆

12 . 5.0³/₄ =

6 . 4.6 =

1 . 5.7 =

casts

3112 6-B 3112-A

3102-A-B-D

3112 B

3102

3097 6-B-B

3097 6 3093-A 1100-A

3097 7 1800-A

3093-A

3109 I

1098-2-B-C-D


1721 A

3112 B-B-B-B

3112 B-B-B-B

3122 B-B-B-B

Lloyd's Register
Foundation



NW 798-0117