

No. 1146


(Received at London Office,

TESTS OF BOILER STEEL.

Tests of 2 Steel plates manufactured by Wardale Iron & Coal Co. of Spangmoor
 for Boiler No. 984 to be constructed by Blair & Co. of London
 for

Date first visit Jan 9th 88 last visit ✓ No. of visits one

The plates specified in the accompanying copy of Advice Notes were rolled from one charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests have proved satisfactory.



When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
	<i>Fire Box</i>	<i>4693</i>	<i>2</i>	<i>A</i>	<i>.60</i>	<i>1.55</i>	<i>.930</i>	<i>25.66</i>	<i>27.50</i>	<i>22.00</i>	

SP 3/1/88

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by

© 2021
Henry Wilkinson
 Surveyor, Lloyd's Register
West. Hartlepool