

Received by Chief Surveyor

30.9.96

Received from Chief Surveyor

VESSEL'S NAME

S. S. Tadorna

Report

Howe No. 33877

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

It is submitted that before this case receives the consideration of the Committee, the Surveyor (M. Sibson) should be requested to state whether the thickness of the side girders is correctly stated on his report, in view of the upper edges of these girders being flanged in which case the Rules require the ~~plating~~ to be increased 1/20" in thickness.

Rpt to Howe
30/9/96

W.M.
30.9.96
C.S.F.



© 2021

Lloyd's Register
Foundation

NW849-0009