

F.E.

Received by Chief Surveyor 2.10.96

Received from Chief Surveyor

SHIP'S NAME Steel S.S. Tadorna

Report Twc No. 33877

Remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>2/20"</u>	<u>Proportions</u>
Spar Sheerstrake . .	_____	_____
Description of Framing:— <u>Ordinary framing</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **✠ 100 A I "steel"**

✠ 100 A I "steel"
2 Dks (1 Iron) "Well deck"
WB = Cell & Ba 69', 83' 200 t
BK 9" Cem

W.M.
2.10.96
C.R.F.



© 2021
Lloyd's Register
Foundation

NWC849-0013

Quarter, 'tween Dks., " "	Forecastle Deck Stringer Plate, breadth & thickness
" " in Hold " "	" Angle on ditto.