

Reference

M.

LLOYD'S REGISTER  
LONDON.

REC'D

ANS'D

11 JUL 1901

+

Lloyd's Register of British  
and Foreign Shipping.

3, St. Nicholas Buildings, Newcastle on Tyne.

18<sup>th</sup> July 1901.The Secretary  
London.

Sir,

In reply to your letter of the 9<sup>th</sup> inst.  
re. S.S. "Eider" I beg to state that the  
Stream Anchor was sent to the Provvy House  
at Low Walker to be tested but the stock  
not being satisfactory the Anchor had  
to be sent to Messrs Abbotts to be repaired  
& is at present at their works.

After the repairs are completed the Anchor  
will be tested & Certificate forwarded.

The Owners have not yet been able to wire?  
find a Certificate for the steel stream chain  
but hope to get same on vessel's return  
to the Tyne in about a week time.

All particulars will be forwarded



whenever received at this office.

I am, Sir  
Your obedient Servant  
A. B. Sweden.



© 2021

Lloyd's Register  
Foundation

NWC875-0087 2/2



Referred to the Chief Ship Surveyor.

11 JUL 1901

*afw*

*Also for Mr. Hill to note.*

*C. X. p.*  
*11/7/01*

*Received  
for the Chief Surveyor  
11/7/01*

*11/7/01*



© 2021

Lloyd's Register  
Foundation