

Lloyd's Register of British  
and Foreign Shipping.

Sunderland. May 6<sup>th</sup> 1842

Charles Graham Esq<sup>r</sup>

Sir

In reply to your enquiry respecting the  
number of Hula Beams in the Ship No 2165, I have to say  
the recommendation of the Committee page 11 was pointed  
out to the Builders who thought it not necessary to carry  
it out from a fear of heaking stowage, you'll observe this vessel  
is truss'd to the bilge on each side and well fasten'd —  
both in the upper and lower deck range, quality of material  
of the very best description, and scantling large throughout —  
there are other Builders in this port who object to the carrying  
out of this recommendation — And remain Yours &c

Thos. D. Smiley



Lloyd's Register  
Foundation