

May 17/59

We are of opinion that about twenty additional through Bolts of Copper or Yellow Metal placed at the discretion of the resident Surveyors on each side will fully compensate for the too small diameter of those already driven.

Should the Committee approve of this recommendation Mr Wm Pile has promised to comply with the same

J. H. R.



© 2021

Lloyd's Register Foundation

SLD934-0061

The Stem, and Stern Post, consist of English Oak & Yew The Transoms, and