


RECEIVED 20th JAN. 83

entered  
29/1/83

M  
26/1/83

Transp. J. Tricamo's report No. 13. 11. 83.


Proposed Arrangement of Ballast Tank Pipes  
Toward Pumps Sluice Valves in No. 6. S.S.



WA. 30. 1. 83  
J.S.  
30/1/83



No 6



Plan of the  
(unintelligible)

Section 3

After Tank Section 3

Section 2 After Well (in tunnel) 2 1/2"

Section 3

Plan of the  
(unintelligible)



© 2021

Lloyd's Register  
Foundation

SLD946-0014