

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 4048

(Received at London Office)

TESTS OF BOILER STEEL.

Tests of 1 Steel Plate manufactured by Messrs Colville Sons of Motherwell for Boiler No. 567 to be constructed by Messrs The North Eastern M.E. Co of Sunderland for Messrs J. Blumer & Co's S.S. No. Date first visit March 24th 1888 last visit March 30th 1888 No. of visits


The specified in the accompanying copy of Advice Notes were rolled from charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests to a shearing from the plate with satisfactory results

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	21.8 x 65 3/4 x 1 9/32	A495		5694	1.30	1.04	1.352	40.10	29.6	26.5	A495 6.4.88.

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by



© 2021

H. N. Dove

Surveyor, Lloyd's Register,

Glasgow
30.3.88