

Tops Lam March 14-1857

George B Seyfang Esq  
Sir

As there were <sup>little</sup> more than 1/3<sup>rd</sup> English Elm Floors and all English Oak just felled, and the floors that are there all in the dead flat I recom-  
mended to be 1 for the Jeffrey

English Elm Floors are not so stiff as Oak but for durability in the flat are equal to Oak, I repaired an old vessel of my own some time since she had half English Elm floors and half English Oak the vessel was 40 years old and the Elm floors perfect, The Majestics



Floors are Birch and Hackmatack  
I think the Birch floors are  
not more than  $1\frac{1}{2}$  the length  
of the ship

I remain Sir  
your Obedt Serv<sup>t</sup>  
Sol<sup>r</sup> H. H. H. H. H.

one would think the  
length of the ship  
not more than  
1 1/2 the length  
of the ship

one would think the  
length of the ship  
not more than  
1 1/2 the length  
of the ship



© 2021

Lloyd's Register  
Foundation



Flo  
Pa  
no  
of

1857

14 March

Topolham

M. W. H. H. H. H.

Rev 16

Am




George B. Seyfang Esq

Agents Register Office

Landover

May 1857

*[Signature]*



© 2021

Lloyd's Register  
Foundation