

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME WELLINGTON STAR Report LW. No. 113883**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey Condition & Closing of When due —
Tonnage openings

Noted.

AES
8.3-40

Command in RB:- 2 Dks & Shelter dks
 8 BH
 (coll BH 6 sh. dks 7BH 6 2nd dks)

to 3 Dks
 8 BH
 (coll BH 6 W. dks 7BH 6 2nd dks)
 to upper 'tween dks BHs except Coll BH
 dispensed with.



Lloyd's Register
 Foundation

(see endorsement 13/1/40
 on Foreward Rpt 35612)