

t Long. No. 2640

Depth "d" -

3873 (2 LINES).

20 SEP 1944

X.R.

## Lloyd's Register of Shipping,

Ocean Chambers, Lowgate,

Hull, 19th September, 1944.

Dear Sir,

In reply to the enquiry contained in your Classing Letter of the 1st August regarding the "ENTICER", our Report No. 52519, we beg to inform you that the rating of the dynamo is 183 amps at 400 revs., and it is regretted that owing to a typing error an incorrect rating was given in our Report.

We are, Dear Sir,  
Yours faithfully,  
The Surveyors,  
Per:-

The Secretary,  
WOKINGHAM.

*W. G. Connell*



© 2020

Lloyd's Register  
Foundation

Extreme breadth over belting 36.0'

E.S.D.

1  $\frac{3}{4}$ "



L

H

*Noted by  
2/20/9/66*

*LLP*

20 SEP 1944

Let:-

the following information  
is being furnished to you  
for your information.

The following information was given to our records.  
It is being furnished to you for your information.  
The following information is being furnished to you  
for your information.

20 SEP 1944

20 SEP 1944

20 SEP 1944

20 SEP 1944



© 2020

Lloyd's Register  
Foundation

36873 (21)

LONG.