

REPORT OF SURVEY FOR REPAIRS &c.

F REPORT OF TOTAL LOSS, CASUALTY, &c.

No. 76015 in R. B. Wreck Book, p. 68/41

Date of writing this report 19

Vessel's Name *S.S. Homefield* of *Glasgow* Tons {Gross 5324Built at *Sunderland* When *1919* 5 Casualty notice sent to Owner *X* Owner's reply *4*Owner's Name *British India Steam Navigation Co. Ltd.*Address *122, Leadenhall Street, London, E. C. 3*

SOURCE OF INFORMATION.

Case previously before
Classing Committee. { Date
Last Minute

Particulars of Classification.

+ 100 AT + LMC 1238

10,40 BS 10,40

SS. Cal. N^o 3-1238 T.S. 10,40CLDate of Casualty *About 6th April, 1941.*Précis of particulars of Casualty *Sunk by aircraft about the 6th April, 1941.*

TS. - 5/34 - *Liner packed*
10/28 - *Liner not packed*

Suggested Record

OMITTED FROM R.B.


Date of Committee

20 MAY 1941

Committee's Minute

OMITTED FROM R.B.

570 40 *large balls not fitted*
Wink Cal *BS 10.40/26*



© 2020

W1004-0024

Lloyd's Register
Foundation

W1004-0027