

LOYD'S REGISTER
LONDON
20 APR 1914

A. C. HERON,
SURVEYOR.

TELEPHONE NO. 7227

G.P.O. Box 333

Lloyd's Register of British and Foreign Shipping,

17 BRIDGE STREET,

SYDNEY, N.S.W.,

16th March, 1914

The Secretary,
Sir.

In reply to your
letter of 13th Feb Re watertight doors on
T. & S. "Sea of Victoria", beg to state that
Mr. Robinson called on board this morning
and found coal in Cross Bunker, and
more coal proceeding in this Cross Bunker.
The doors could not therefore be properly
examined, and the Chief Officer and
Chief Engineer had not received any instructions
that the watertight doors in question had
to be pumped here, there with therefore,
have to be examined on vessels arrival
at a home port.

Yours
Dear Sir

Yours obedient servant
A. C. Heron.



© 2019

Lloyd's Register
Foundation

W1005-0016

Referred to Mr. S. A. Hill

APR 20 1914



© 2019

Lloyd's Register
Foundation

The Surv
MELBO
SYD

the vo
were n
Superi
Superi
is pro

have I
of the
you wh

vesse

CROSS

doors

100A1

"STAR

SH