

Owners. ~~Security Vacuum Oil Co. Inc.~~ Owners' Address. -
(if not already recorded in Appendix to Register Book).
Managers. United States War Shipping Administration Port belonging to New York
at or in Dry Dock? Both Name of Dock Todd Ship. Corp. Destined Voyage -

POSTPONED SURVEYS.

Case of the S.S. "BIRKENHEAD".

No. 70676 in Reg. Bk. _____ tons, Built _____

Classed _____ Owners _____

Port of Registry _____

Survey Due General Examination due 1.45.
Boiler Survey due 1.45.

The New York Surveyors state they have been informed that this vessel is under bareboat charter to the United States Navy and the U.S.W.S.A. are unable to state when and where she will be available for outstanding surveys.

SUBMITTED action be deferred subject to outstanding surveys being carried out when vessel is redelivered to Owners.

GAH Bell.
1.2.45

FRI. 9 FEB 1945

Committee's Minute _____

Decision _____

Deferred

(Treat as Birt. adm. Case)

5c,9,44

[Signature]



© 2021

Lloyd's Register

W1006-0073

Observations, Opinion as to Class, Recommendation, &c. :-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon the survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

(which must be in & Supplements)

Machinery and Boilers Surveys including date of N.B.

MC 7,41

SS 2,43

TS CL 8,4

in bulk.

1 10,21

F.

5 ft.

5 S.R.

re damage

ned, exami

way of

P&S, dr

bottoms c

aks caul

s ranged

cofferdam

and summe

heads wer

s with t

Good

"

certained from

(removed.)

2B, 1S

ow ranged)

O fms mean

"

Good

"

ing Riggings

"