

...age cases where the Surveyor has not made a special damage report he is required to state whether he
ferred his services for this purpose and to whom and why they were declined- **COPY ATTACHED**

Fitted for oil fuel
above 150°F
Society's Freeboard (if assigned) as
painted on Ship and now verified

MEMORANDUM

From: LLOYD'S REGISTER OF SHIPPING, HIGH CLOSE, WOKINGHAM.

(Ref. H)

Wm. Bennett, Esq.,

To: The Surveyor(s) at

NEW YORK.

Date: 24th November, 1944.

Vessel's Name: "BIRKENHEAD".

Question: I shall be glad if you will ascertain and let me know what
arrangements are proposed to be made to carry out the General Examination
for maintenance of class which requires to be held by the end of January
next.

**You will observe that the Boiler Survey also becomes due at that
time.**

Answer:

Date: January 4, 1945

The W.S.A. advise that this vessel is under bareboat charter
to the U.S. Navy and they are unable to state when and where
she will be available for the outstanding surveys.



© 2021

Lloyd's Register
Foundation

W1006-0074

W1006-0075

" in way of sidelights "

Windlass

Hatches

Yards, &c.

Conclusion, how ascertain
(State if wedges rem