

2nd Long. No. 15790

Proportions = $\frac{L}{D}$ 11.13

ONE: MIDDLESBRO' 43431-2

Lloyd's Register of Shipping,

RECEIVED

6 AUG 1948

Lloyds Bank Chambers,

Middlesbrough, 5th August, 1948.

Dear Sir,


We are in receipt of your classing letter of the 29th ultimo, regarding Middlesbrough Report No. 18539 on the "BERGSUND", and in reply have to state that a spare lubricating oil pump is fitted in addition to the main engine lubricating oil pump.

Yours faithfully,
The Surveyors,

Per:-

Robert Stuart

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

W1006-0118

FE 18/7

E.S.D.V

"9"

23"

24"

50
Disferred to Mr. Penin

Handwritten signature or initials.

v/s Haw 30/7 dam

~~For Engineer Surveyors (F.E. Rpt.) to notes~~

Noted. Ent. 9/8/48

COBY.

RECEIVED
SEP 10 1948



© 2021

Lloyd's Register
Foundation

1st L
2nd L
Framir
oper
requ
be cla
Rules
Freebo
insert
Book, e
extrac
1 Dk &
Cell DE
FK, 4BH
F 31,
O.L. 28
E.S.D.v
"ng"
1 3/4