

to Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME..... EASTERN CROWN..... REPORT..... N.Ns..... No. 5989


For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER-SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey..... DOCKING AND REPAIRS..... When due.....

Subject to indented shell plates in
F & G strakes (s.s.f) and indented bottom plating
etc. (p.s.f. & s.s.a) being dealt with at the
first convenient opportunity.

7,46 N.Ns


11.9.46



© 2020

Lloyd's Register
Foundation

W1009-0025