

52,8,11.

F.E.

Received by Chief Ship Surveyor 27/2/11

Received from Chief Ship Surveyor _____

VESSEL'S NAME At H "Emma"

Rpt. Bel

No. 7024

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 79.5

Depth "d" 15.9

Framing: Table No. 2 page 7

Description Frame transverse frame

Longitudinal No. 32595

as approved.

Proportions Length = 11.6
Depth = _____

Shade Deck Sheerstrake as per Rule

RETAIN

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100 A-1. (Shade) Shade deck, as recommended.

+ 100 A-1. (Shade) Shade deck

2nd Deck (20 2nd WS) Shade deck (2nd Deck)

WB. bul 8 3/4 76 u 8 1/2 108 f 15 6 732 t FBT 586 APT 446
FK. 7 BH 5 BH to 2nd Deck 2 BH to 2nd Deck. Lloyds at 60
B on Shade deck 15 6

W1009-0071

© 2020
27/7/11
Lloyd's Register
Foundation