

The class is subject to a spare propeller being supplied.

5 E

15 DEC 1948

ed by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SEL'S NAME "KATOWICE" REPORT Gdy. No. 2167

emarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

~~DAMAGE &~~ WEAR AND TEAR.

Ballast and feed pumps have been overhauled.

It is submitted the vessel is eligible to remain as classed, with
~~record of survey~~
as recommended. Subject as above.

15 12. 48.

Lloyd's Register
Foundation