

COPY

W1012-0089

Lloyd's Register of Shipping.



At this survey the brine pipes were
satisfactorily tested to one and a half
times the working pressure at the brine
circulating pumps.

Port BUENOS AIRES

6th. April, 1949.-

LOADING CERTIFICATE FOR VESSELS HOLDING LLOYD'S REFRIGERATING MACHINERY CERTIFICATE.

This is to Certify that the Survey
required by paragraph 11 (as printed on the back hereof)
of the Society's Rules as to Refrigerating Machinery and
Appliances has been held by me at this port on the
Refrigerating Machinery and the Insulation and Appliances
of the undermentioned spaces

of the T.S.S. "MAGDALENA", 17000 tons gross of London
which has the record LLOYD'S RMC 2,49 in Lloyd's Register
Book.

On such Survey, I found the insulation undamaged and
clean, the ^{Portable} dunnage battens, where these are required, in good
order, and the Refrigerating Machinery, when tested under
working conditions, also in good and satisfactory order.

I have transmitted to the Committee of Lloyd's Register
of Shipping, London, a Report stating that all recommen-
dations made by me have been completed to my satisfaction.

Before loading was commenced, the tempera-
ture of cargo chambers was reduced as follows:—

Upper Tween Dk.	15°F	Trunk	11°F	N°2 Lower Hold
N°1 Main Tween Dk.	14°F	Trunk	8°F	N°2 Orlop Dk. Port
N°1 Lower Tween Dk.	16°F	Port	12°F	N°2 Orlop Dk. Starboard
N°1 Lower Hold	16°F	Starboard	12°F	N°3 Main Tween Dk.
N°2 Main Tween Dk.	15°F	Starboard	14°F	N°3 Lower Tween Dk.
N°2 Main Tween Dk.	14°F	Trunk	14°F	N°3 Lower Tween Dk.
N°2 Lower Tween Dk.	14°F	Starboard	15°F	N°3 Orlop Dk. Port
N°2 Lower Tween Dk.	14°F	Trunk	8°F	N°3 Orlop Dk. Starboard

and in my opinion the vessel is fit to
during the contemplated voyage to U

at
Survey

This Certificate is issued upon the terms of the Rules
provide that:—

"While the Committees of the Society use their best endeavours
to properly execute their duties, it is to be understood that neither the
Committees is under any circumstances whatever to be held responsible
for any error of judgment, default or negligence of the Society,
or for any error of judgment, default or negligence of the Society,
thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2020

Lloyd's Register
Foundation