

Owner's Name

Address

WRECK SECTION

No. 541.....

BARRELL & CO.

SOLICITORS
COMMISSIONERS FOR OATHS.

W. P. BARRELL, LL.M.

INCORPORATING { BYERS DIXON & BARRELL.
EATON SON & WILLIAMSON.

20, CASTLE STREET,

LIVERPOOL, 2.

Barrell

TELEGRAMS: "BARRELL LIVERPOOL"
TELEPHONE: CENTRAL 9168

RECEIVED

12 MAY 1948

ANSO..... 12.....

11th May, 1948.

Dear Sir,

Re: 46257/M - m.v. "MATRONA".


We thank you for your letter of the 10th instant and note that we seem to be under a misapprehension that Mr. McIntyre, the surveyor to the Society was stationed in Liverpool in October last when the above ship overturned.

We are not so much concerned whether Mr. McIntyre was actually in this city when the vessel overturned, but we are interested to know whether Mr. McIntyre did certain survey work on the vessel before it overturned. If this is so we are wondering whether you would be so kind as to grant us facilities to see *Mr* McIntyre.

If Mr. McIntyre was not concerned with the above vessel would you be so kind as to advise us who the Lloyd's surveyor was, concerned, and thereafter grant us facilities to see him.

We enclose herewith stamped addressed envelope for your reply.

Yours faithfully,



The Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street,
LONDON, E.C.3.

CH/HC.



© 2020

Lloyd's Register
Foundation

Referred to Mr. Clement.

Pt. 6.

Submitted the written informed
statements to Clerk Registrar and
not permitted to give evidence or make any
court records on a promissory case except in
five of the Society's Seminars. CB
ruled the vessel would under
Seminars in 2nd week of 1947
No case there



© 2020

Lloyd's Register
Foundation