

MEMORANDUM

LOYD'S REGISTER OF SHIPPING, 71, FENCHURCH STREET,
LONDON, E.C.3.

(Ref. H)

Surveyor(s) at **NEWCASTLE-ON-TYNE.**

Date: **12th February, 1948.**

Name: **S.S. "HOPESTAR".**

QUESTION.

ANSWER.

reference to the entry in
Official Reasons List, I shall be
you will ascertain and let
what arrangements the Owners
making for the thermal engine
shaft to be renewed, as recommended
Liverpool Surveyors in September

Date:— **20th February, 1948.**

We attach for your
information a copy of a communication
received from the Owners of this
vessel in reply to our enquiry
respecting the Thermal Engine
Crankshaft.

THE SURVEYORS,

per:—

ENCLOSURE:— 1 letter (copy).

B.A.S. Flimney 11/2/48

© 2020

Lloyd's Register
Foundation

er Bottom Plating	examined and found efficient?	at other places
re the Tanks been examined internally?	Air and Sounding Pipes	Stringers, Clamps & Shelves
ave the Tanks been tested?	Doubling Plates under Sounding Pipes	Salting
		State if examined.