






### how done for Damage (2)

Forecastle rails port side part removed fused & refitted  
Holed deck stringer plate doubled.

The owners proposal to defer repairs to the W4 Damage in my opinion merits approval.

Nothing was done at this time to the outstanding items as per S.R. list.



When Anchors or Cables are supplied, the particulars are to be reported in the following form :—

## ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd "																
	3rd "																
	Collective Weight																
	Stream.....																
	Kedge .....																

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

## CHAIN CABLES.

[illegible]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.