

offered his services for this purpose and to whom and why they were declined

Services

Society's
painter

offered but not required.

Was a damage report made by anyone else? if s

COPY

27th December, 1945.

Dear Sirs,

I have to acquaint you that I am in receipt of a communication from the Owners of the steamer "HOPESTAR" in which they state that the vessel is now in the Tyne where they are hoping to carry out the General Examination for maintenance of class and the Loadline Renewal Survey, which require to be held by the end of February next.

In the circumstances I shall be glad if you will give the case the necessary attention.

Yours faithfully,

Clerk to the
Classification Committee.

The Surveyors,
NEWCASTLE-on-TYNE.



© 2020

Lloyd's Register
Foundation

W1013-0062

Inner Bottom Plating.....	Air and Sounding Pipes.....	Salting
Have the Tanks been examined internally?.....	Doubling Plates under Sounding Pipes	(State if examined.)
Have the Tanks been tested?.....		

General Observations, Opinion as to Class, Recommendation, &c.: