

**Particulars of Classification** (*which*  
*precisely as in Register Book*)

CHARACTER.	Years Assigned expired.
✱ for Special Survey. Date of last Survey and of Periodical Surveys.	

LONDON OFFICE:  
BUSH HOUSE, ALDWYCH

NOT  
OF REPORT)

TELEPHONE :  
ALTRINCHAM 3381 (2 LINES)

Lloyds Register of Shipping,  
71 Fenchurch Street,  
LONDON, E.C.3.

19th May, 1941.

Dear Sirs,

s.s. "HOPESTAR" - REPLACE COMBUSTION CHAMBER ELEMENTS,  
AND CONNECTING PIPES.

Further to our letter of the 15th instant we now enclose three prints of each of our following drawings :-

MB.14300 - Detail of Elements.  
8921/40 - Detail of Connecting Pipes.

The elements and connecting pipes are similar to those we originally supplied to your inspection and tests at our Works, and in this instance are to be made from solid cold drawn mild steel tubing in stock at our Works 1.3/8" o.d. x 9 w.g. thick, made by one of our usual suppliers to our Specification X42. Mechanical test and chemical analysis certificates being available at our Works.

We should be obliged to have one of each of the enclosed prints stamped as approved and returned to us in due course.

Yours faithfully,  
FOR THE SUPERHEATER COMPANY, LIMITED.

ENCL.

W1013-0135

3-0135 Lloyd's Register  
Foundation  
your class  
ited plating  
P. M. L. T.

between Nos 1 and 2 holds being dealt with at Owner's convenience, and indented shell plating and fr  
to repair permanently first convenient opportunity as previously recommended. Also to scupper pipe. PE



Referred to the Chief Engineer Surveyor.

MR

21 MAY 1941



© 2020

Lloyd's Register  
Foundation