

to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

13 AUG 1941

SEL'S NAME \_\_\_\_\_

Hope Star

Report \_\_\_\_\_

Nyk

No. 42608

For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

No Boilers

SURVEY PARTLY HELD. 5.42 how partly reheld.

on due \_\_\_\_\_

P. 42.


When proposed to be completed \_\_\_\_\_

not stated

tion of Survey held, &amp;c.

Note  
h

Examine donkey, boiler & mountings (except capst., valves)  
+ adjust all capst., valves.

© 2020  
Hobart  
Kew

13.8.42

W1013-0239

Lloyd's Register  
Foundation