

JOHN WILLIAMS.

THE LLOYD AGENTS SUVA SHOULD BE  
INFORMED BY CABLE AS FOLLOWS:-

ORIGINAL SHELL THICKNESS IN HUNDRETHS

A, B, C MIDSHIPS 50 ENDS 45 D

MIDSHIPS 25 BUNKERS 30 ENDS 23.

E MIDSHIPS 42 FORWARD 30 AFT 27.

THICKNESSES INCLUDE OWNERS

INCREASE IN HUNDRETHS A 17

B 20 C 25 MIDSHIPS A 15

B 19 C 22 ENDS."

J MacE  
20/12/47



© 2019

Lloyd's Register  
Foundation