

Lloyd's Register of Shipping.



Port SUVA, FIJI

This is to Certify that I have

Surveyed the Motor Yacht. "JOHN WILLIAMS V"

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be Reclassified with a fresh record of Survey and notation 2nd S.S. No.1 3/48.

being fit to carry Passengers and cargo in accordance with local regulations.

Paul Lury

Surveyor to Lloyd's Register.
SURVEYOR APPOINTED BY LLOYD'S AGENTS.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

5. T.

Age or Repair Fee (if any) £ :
per Section 29.)

expenses (if chargeable) £ : :

Received by me,
24: 3: 19 48

FRI, 30 APR 1948

Engineer Surveyor to Lloyd's Register
SURVEYOR APPOINTED BY LLOYD'S AGENTS.